



Instruction Manual For HE-2 Kit
(Replacement for 944417 sensor)

136603 HE-2
2-WIRE TO
3-WIRE CONV.
SENSOR EXTRA




Step 1 Cut the resistor R17 as shown in the picture



Step 2 Wiring Specifications

Red	+12 V	TB1-1 From Left
White	Signal	TB3-1 From Left
Black	GND	TB3-2 From Left



Step 3 Connections to the monitor

Wiring Diagram for STM 94442 to NP64 Board

